Work Order



WORK ORDER INFORMATION

Work Order Name: WO/70007HR2275/1
Work Order Type: Weatherization
Audit Name: Audit (85)

CLIENT INFORMATION

Client Name: Address:

Client ID: 70007HR2275

Alt. Client ID:

AGENCY INFORMATION

Agency: HREC Agency Phone: (931) 289-4101

Address: P.O Box 208

Agency Contact: Adamson, James R Work Phone: (615) 478-1355

Cell Phone: (615) 478-1355

Email Address: jamieadamson@rocketmail.com

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Work Order By: James Adamson

Blower Door 50 Pascals @ 2953 CFM's

House Age 1970 / 1323 SF

Measure 1 Infiltration Redctn Comment Air Infiltration. 1. Install the following items on kitchen door leading to closed in carport: A. Kwickset door lock assembly. Currently the door has no lock assembly and cannot be closed.

- B. Weather-strip and door sweep.
- C. Caulk door frame and trim, both sides with clear paintable caulk.
- 2. Caulk around old attic access in rear bedroom closet.
- 3. Caulk crown in kitchen with clear paintable caulk. Room size 18' x 11'

		Estimated		1		Actual		
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Supplies	Infiltration Reduction	Each	3					
Other Detail								
		Ме	asure S	ub Total:		S	ub Total:	
Field Notes:								

Measure 2 Storm Windows Comment Window Size 39" x 67"				Componen		Inspected		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Storm Window	Each	1					
2 Labor	Storm Window	Each	1					
3 Other	Storm Window	Each	1					
Other Detail								
		Меа	asure S	ub Total:		S	ub Total:	
Field Notes:								
Measure 3 Wir	ndow Sealing			Componen	te WD1	(5)		Inspected
Comment 1. Wea	_			Componen		(0)		
2.Insta	ll small wood trim on right	hand side	of wir	ndow and ca Estimated		oaint trir	n. <i>Actual</i>	
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Window Sealing	Each Window	1					
2 Labor	Window Sealing	Each Window	1					
10 Miscellaneous Supplies	Total Added Misc Cost	Each	1					
Other Detail								
		Mea	asure S	ub Total:		S	ub Total:	
Field Notes:								

		H Pipe Insulation ve Feet Mandatory.			Componen	ts			Inspected
	omment i ist i i	ve i eet Mandatory.			Estimated	1		Actual	
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
C	Other Detail]	
L									
]	
			Me	asure S	ub Total:		S	ub Total:	
		H Tank Insulation			Componen	ts			Inspected
C	comment				Estimated	1		Actual	
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	DHW Tank Insulation	Each	1					
C	Other Detail							1	
L									
			Me	asure S	ub Total:		S	ub Total:	
	Field Notes:								

Measure 6 Floo Comment	or Ins. R-19			Componen Estimated			Actual	Inspected
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R- 19	SqFt	975					
Other Detail								
		Ме	asure S	ub Total:		S	ub Total:	
_	lace A/C homeowner on where to ir	nstall un	it.	Componen			ı	Inspected
				Estimated			Actual	
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipment	Repalce A/C. w/heat strip.	Each	1					
1 Cooling Equipment	Replace A/C. w/heat strip.	Each	1					
Other Detail] [
		Ме	asure S	ub Total:		S	ub Total:	
Field Notes:								

	Ins. R-38			Componen	ts A1			Inspected
Comment Include u	pgrade attic hatch accor	ding to S	.W.F.G	i.				
Include s fiberglass	tyrofoam baffles and pac s batts.	ck voids t	etweei	n baffles an	d top pla	te with		
_				Estimated	1		Actual	
# Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Attic Insulation - Cellulose, Blown - R-38	SqFt	1323					
Other Detail							1	
		Me	asure Su	ub Total:		S	ub Total:	
Measure 9 CO M								
	lonitor is Needed		ı	Componen	ts			Inspected
Comment	lonitor is Needed			Componen Estimated			Actual	Inspected
	Ionitor is Needed Description /Comment	Units	Qty	-		Qty		Inspected
Comment # Material / Labor		<i>Units</i> Each		Estimated	<u>'</u>	Qty	Actual	
# Material / Labor 1 Health and Safety Items	Description /Comment		Qty	Estimated	<u>'</u>	Qty	Actual	
# Material / Labor 1 Health and Safety Items	Description /Comment CO monitor	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description /Comment CO monitor	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description /Comment CO monitor	Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
 Comment # Material / Labor 1 Health and Safety Items 2 Labor 	Description /Comment CO monitor	Each	Qty 1	Estimated	<u>'</u>		Actual	

	Measure 10 Pres	sureRelief Piping Ne	eded		Componen	ts			Inspected
C	comment Extend t	o exterior of home. W	ater heater is	s on ex	terior wall. <i>Estimated</i>			Actual	
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Pressure relief piping	Each	1					
2	Labor	Labor	Hour	1					
	Other Detail								
L			Mea	asure S	ub Total:		S	ub Total:	
	•	or Barrier Needed ement/Crawlspace)			Componen	ts			Inspected
C	Comment	,							
					Estimated	'		Actual	
#	Material / Labor	Description /Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Basement / crawlspace vapor barrier	e SqFt	975					
2	Labor	Labor	SqFt	975					
C	Other Detail							1	
L									
			Mea	asure S	ub Total:		S	ub Total:	
	Field Notes:								
			Work Orde	er Grand	l Total:		Grand	l Total:	